

## 6 MONTHLY VISUAL INSPECTION & FUNCTION CHECK

Doc Ref: SADS-IMS-FM-93 Issue 01 Issue Date: 18/06/2020 Issued By: P. Curtis

SADS ID	DSV-ANCILS-6M-04	
ITEM LOCATION	DSV Curtis Marshall for duration of diving project	
ITEM DESCRIPTION	DSV Ancillary Equipment	

Item Description	SADS ID	Visual/Function Check Info	Defects or Notes	Tech Initial
Diving Helmet		Visual examination & function test including comms Check Certification 'in date' Annual Overhaul	IMCA D018 Ref 5.3	N/A For Project
Standby Hat		Visual examination & function test including comms - Check Certification 'in date' Annual Overhaul	IMCA D018 Ref 5.3	N/A For Project
1 <sup>st</sup> Stage Reducers	SADS-REG-08	- Visual examination & function test  - Comparison checks of contents gauge with calibrated cylinder gauge.  - Check Certification 'in date' Annual Overhaul	IMCA D018 Ref 5.3	DZ
Umbilicals	SADS-UMB-06 SADS-UMB-07 SADS-UMB-08	- Continuity Check of comms, lights, & camera - Visual Inspection & Function check - Blow through to remove any moisture - Re-tape depth markings as required - Check Certification is 'in date' 2 Yr Leak test to working pressure.	IMCA D018 Ref 11, 28	02
Bailout Bottles		- External Visual Examination - Fully operate cylinder valve - Charge to WP and check for leaks - Check certification is 'in date' V & H	IMCA D018 Ref 10.1	N/A For Project
Bailout Jackets	75	Check for signs of corrosion or damage - Check weights release system - Check cylinder securing system - Check for rips, tears, fraying	IMCA D018 Ref 35	N/A For Project
Diver Recovery System		Visual examination for corrosion/damage. Function test at max SWL. Check brake system at 1.25 X SWL.	IMCA D018 Ref 22.1, 3	N/A For Project

Sub Aqua Diving Services UK Ltd

E: enquiries@commercialdivingservices.co.uk
W: www.commercialdivingservices.co.uk



## 6 MONTHLY VISUAL INSPECTION & FUNCTION CHECK

Doc Ref: SADS-IMS-FM-93 Issue 01 Issue Date: 18/06/2020 Issued By: P. Curtis

DMAC Medical Kit	SADS-DMAC (A) SADS-DMAC (B) Chamber Med Kit	Visually inspect for cleanliness & check in date		PZ
First Aid Kit		Visually inspect for cleanliness & check in date		N/A For Project
O2 Set		Visual examination & function test. Check set is fully charged	IMCA D018 Ref 10.1, 5.1	
Defibrillator	SADS-DSV-AED-01	Visual examination & function test. Check set is fully charged		DZ/DC
Stretcher and lifting bridle	SADS-RECOVERY-03	Visual examination of system for damage and wear to bridle and stretcher	IMCA D018 Ref 03	NG

I hereby certify that the above items have been visually examined and had a full function check where required. Any defects found are to be recorded on the fault-reporting sheet.

Once completed return to Document Controller to be uploaded and filed

DATE OF INSPECTION	01st Feb 2022	NEXT DUE DATE:	31 <sup>st</sup> July 2022
	A STATE OF THE PARTY OF THE PAR		PERSON AT

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

Sheet left intentionally blank; will be populated prior to next diving project. All checks on equipment numbered in this form have been completed and certification updated.

Tech Dept
Supplingustamp
Diving Services

Sub Aqua Diving Services UK Ltd

E: enquiries@commercialdivingservices.co.uk
W: www.commercialdivingservices.co.uk