

6 MONTHLY VISUAL INSPECTION & FUNCTION CHECK

Doc Ref: SADS-IMS-FM-93
 Issue 01
 Issue Date: 18/06/2020
 Issued By: P. Curtis

| | |
|-------------------------|--|
| ITEM DESCRIPTION | DSV Ancillary Equipment |
| ITEM LOCATION | DSV Curtis Marshall for duration of diving project |
| SADS ID | DSV-ANCILS-6M-08 |

| Item Description | SADS ID | Visual/Function Check Info | Defects or Notes | Tech Initial |
|--------------------------------|--|--|----------------------|-------------------------|
| Diving Helmet | SADS-KM-10 SADS-KM-11 | Visual examination & function test including comms Check Certification 'in date' Annual Overhaul | IMCA D018 Ref 5.3 | NOT ON HIRE DZ |
| Standby Hat | SADS-KM-03 SADS-KM-02 | Visual examination & function test including comms - Check Certification 'in date' Annual Overhaul | IMCA D018 Ref 5.3 | NOT ON HIRE DZ |
| 1 st Stage Reducers | SADS-REG-02 (KM-02) SADS-REG-03 (KM-03) SADS-REG-07 (KM-10) SADS-REG-09 (KM-11) | - Visual examination & function test - Comparison checks of contents gauge with calibrated cylinder gauge. - Check Certification 'in date' Annual Overhaul | IMCA D018 Ref 5.3 | NOT ON HIRE DZ |
| Umbilicals | SADS-UMB-06 SADS-UMB-07 SADS-UMB-08 | - Continuity Check of comms, lights, & camera - Visual Inspection & Function check - Blow through to remove any moisture - Re-tape depth markings as required - Check Certification is 'in date' 2 Yr Leak test to working pressure. | IMCA D018 Ref 11, 28 | DZ |
| Bailout Bottles | SADS-HPB-07 SADS-HPB-08 SADS-HPB-40 SADS-HPB-41 | - External Visual Examination - Fully operate cylinder valve - Charge to WP and check for leaks - Check certification is 'in date' V & H | IMCA D018 Ref 10.1 | NOT ON HIRE DZ |
| Bailout Jackets | SADS-JKT-02 SADS-JKT-03 SADS-JKT-05 SADS-JKT-06 | Check for signs of corrosion or damage - Check weights release system - Check cylinder securing system - Check for rips, tears, fraying | IMCA D018 Ref 35 | NOT ON HIRE DZ |

6 MONTHLY VISUAL INSPECTION & FUNCTION CHECK

Doc Ref: SADS-IMS-FM-93
Issue 01
Issue Date: 18/06/2020
Issued By: P. Curtis


| | | | | |
|------------------------------|---|--|--------------------------------------|----|
| Diver Recovery System | Winch | Visual examination for corrosion/damage. Function test at max SWL. Check brake system at 1.25 X SWL. | IMCA D018 Ref 22.1, 3 NOT ON HIRE | DZ |
| DMAC Medical Kit | SADS-DMAC (A) SADS-DMAC (B) Chamber Med Kit | Visually inspect for cleanliness & check in date | NOT ON HIRE | DZ |
| First Aid Kit | Ships Supply | Visually inspect for cleanliness & check in date | | DZ |
| O2 Set | SADS-HPB-02-01 | Visual examination & function test. Check set is fully charged | IMCA D018 Ref 10.1, 5.1 | DZ |
| Defibrillator | SADS-DSV-AED-01 | Visual examination & function test. Check set is fully charged | | DZ |
| Stretcher and lifting bridle | SADS-RECOVERY-03 | Visual examination of system for damage and wear to bridle and stretcher | IMCA D018 Ref 03 | DZ |

I hereby certify that the above items have been visually examined and had a full function check where required. Any defects found are to be recorded on the fault-reporting sheet.
Once completed return to Document Controller to be uploaded and filed

| | | | |
|--------------------|---------------------------|----------------|-----------------------------|
| DATE OF INSPECTION | 16 th Oct 2024 | NEXT DUE DATE: | 15 th April 2025 |
|--------------------|---------------------------|----------------|-----------------------------|

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

*Sub Aqua
Diving Services (UK) Ltd*