

**FUNCTION / GAS LEAK / VISUAL
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/ Gas leak/ Visual Inspection
CERTIFICATE NUMBER	SADS-FGV-070
ITEM	MC Light 2 PRV
ITEM DESCRIPTION	Pressure Relief Safety Valve
ITEM LOCATION	DSV DDC Main Chamber
SADS ID	DSV-DDC-PRV-05
TEST DEVICE USED	Druck serial No 3219487 SADS T&T 04

DESCRIPTION of TEST INSPECTION

PRV Seat lifted at 1.3 Bar

REMARKS / RECOMMENDATIONS

Visual examination to be carried out on a 6 monthly basis, see separate sheet

GUIDANCE DOCUMENTS / MANUALSIMCA D018-24.3
IMCA D023. Sheet 3 - Twin Lock Air Chamber. Item 7.20

DATE OF INSPECTION	04 th March 2025	NEXT DUE DATE:	03 rd Sept 2027
--------------------	-----------------------------	----------------	----------------------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE: 