

## FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020

Issue Date: 28/05/2020 Issued By: P. Curtis

TYPE OF TEST / INSPECTION	2 Yearly Function/Gas Leak/Visual			
CERTIFICATE NUMBER	NUMBER SADS-FGV-603			
ITEM	Hale Hamilton RH2 Dome loader			
ITEM LOCATION	DSV /DDC/ Back up			
SADS ID	DSV/DDC/RED/01			

## DESCRIPTION of TEST INSPECTION

- Removed Dome Loader and pipework from quad.
- Overhauled valve and Biox cleaned components.
- Renewed O-rings and washers.
- Cleaned micron filter.
- · Rebuilt all components
- · Flushed through with compressed air.
- Test on system for operation and leaks.
- System set to 12.5 +/- .5 Bar.

## **REMARKS / RECOMMENDATIONS**

6 monthly GVI to be carried out in line with 6 month certification. Daily checks to be carried out prior to each use.

## **GUIDANCE DOCUMENTS / MANUALS**

IMCA D018 - 24.1

DATE OF INSPECTION	4 <sup>th</sup> Jan 2021	NEXT DUE	3 <sup>rd</sup> Jan 2023	
		DATE:		

TECHNICIAN NAME: Neil Graham, Dan Zapalski

**TECHNICIAN SIGNATURE:** 

Sub Agua Diving Services

Sub Aqua Diving Services UK Ltd
E: <a href="mailto:enquiries@commercialdivingservices.co.uk">enquiries@commercialdivingservices.co.uk</a>
W: <a href="mailto:www.commercialdivingservices.co.uk">www.commercialdivingservices.co.uk</a>