

**FUNCTION / GAS LEAK / VISUAL  
TEST CERTIFICATE**Doc Ref: SADS-IMS-FM-92  
Issue 01  
Issue Date: 28/05/2020  
Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual and Cleanliness Verification
CERTIFICATE NUMBER	SADS-FGV-989
ITEM	LP pressure release valve / Sn-168977/8
ITEM DESCRIPTION	Chamber back up supply PRV LP side
ITEM LOCATION	DSV Curtis Marshall
SADS ID	SADS-DDC-RED-PRV-02
TEST DEVICE USED	SADS T&T 03 7 SeeTru Quicktester

**DESCRIPTION of TEST INSPECTION**

- 2.5 yearly function test
- Full Visual Inspection for corrosion & damage
- Valve pressured to blow off pressure of 14.20 Bar.
- Valve re-seated at 13.00

**REMARKS / RECOMMENDATIONS**

6 monthly checks to be carried out IAW asset file paperwork  
Visual and function tests to be carried out as per pre dive checks

**GUIDANCE DOCUMENTS / MANUALS**

IMCA D018 24.3

DATE OF INSPECTION	18 <sup>th</sup> April 2024	NEXT DUE DATE:	17 <sup>th</sup> October 2026
--------------------	-----------------------------	-------------------	-------------------------------

**TECHNICIAN NAME:** Dan Zapalski**TECHNICIAN SIGNATURE:** 