

**FUNCTION / GAS LEAK / VISUAL
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual and Cleanliness Verification
CERTIFICATE NUMBER	SADS-FGV-083
ITEM	Pressure Relief Valve
ITEM DESCRIPTION	DSV Dive Panel PRV
ITEM LOCATION	DSV Curtis Marshall
SADS ID	DSV-DP-PRV-04
TEST DEVICE USED	SADS T&T 03 7 SeeTru Quicktester

DESCRIPTION of TEST INSPECTION

2.5 Yearly

- Full Visual Inspection for corrosion & damage
- Valve pressured to blow off pressure of 24.62 Bar.
- Valve re-seated at 19.25 Bar

REMARKS / RECOMMENDATIONS

6 monthly checks to be carried out IAW asset file paperwork
Visual and function tests to be carried out as per pre dive checks

GUIDANCE DOCUMENTS / MANUALS

IMCA D018 24.3

IMCA D023. Sheet 3- Dive Control. Item- 8.13

DATE OF INSPECTION	05 th March 2025	NEXT DUE DATE:	04 th Sept 2027
--------------------	-----------------------------	-------------------	----------------------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE: 