

FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020 Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual		
CERTIFICATE NUMBER	SADS-FGV-889		
ITEM	Tescom 44 Series Reducer		
ITEM LOCATION	DSV Dive Panel		
SADS ID	DSV-DP-RED-01		
SERIAL No. / MODEL No.	169275-1-007		

DESCRIPTION of TEST INSPECTION

- Full Visual Inspection for corrosion & damage
- 2 Yearly: Gas leak test to maximum working pressure (14 Bar for 15mins)
- Function Test Pressure stable with no creep.
- Cleanliness verified.

REMARKS / RECOMMENDATIONS

6 yearly manufacturers overhaul, carried out 1st May 2019

GUIDANCE DOCUMENTS / MANUALS

Above carried out IAW IMCA D018-24.1

DATE OF INSPECTION	31st July 2023	NEXT DUE	30 th July 2025
1		DATE:	

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:



Sub Aqua Diving Services UK Ltd

E: enquiries@commercialdivingservices.co.uk
W: www.commercialdivingservices.co.uk