

## **Certificate of Service/Maintenance/Repair & Cleanliness**

Certificate No:	SADS/SMR/292		
Item Description:	Tescom 44-1300 series reducer		
SADS ID:	DSV-DP-RED-04		
Date:	2 <sup>nd</sup> May 2019		
Date Due:	2 <sup>nd</sup> May 2025		
Details of work carried out:			
Item	COMMENTS	RESULTS	Initial
Secondary HP reducer to diver 2	Reducer was stripped and sonic cleaned in a 1-20 Biox, solution then rinsed with de-ionised water and dried. The unit was then inspected and rebuilt with new Tescom repair kit (JT389-8535)	Pass with no leakage	NG
<b>Remarks/Recommendations:</b>  6 yearly manufacturers recommended overhaul and test Reducer is clean and fit for service			
Related Certification:			

N Graham  
Technician/Maintainer  
Dive Lab Cert No: T-08488

*N. Graham*  
Signature

2<sup>nd</sup> May 2019  
Date

