

**FUNCTION / GAS LEAK / VISUAL  
TEST CERTIFICATE**Doc Ref: SADS-IMS-FM-92  
Issue 01  
Issue Date: 28/05/2020  
Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/ Gas leak/ Visual Inspection
CERTIFICATE NUMBER	SADS-FGV-088
ITEM DESCRIPTION	Pressure Relief Safety Valve
ITEM LOCATION	DSV-HPC
SADS ID	DSV-HPC-PRV-03

**DESCRIPTION of TEST INSPECTION**

2.5 Yearly:

- Full Visual Inspection for corrosion & damage
- Gas leak test to maximum working pressure
- Function Test – Opened at 103.5 Bar
- Re-seat at 40.6 Bar

**REMARKS / RECOMMENDATIONS**

Visual examination to be carried out on a 6 monthly basis, see separate sheet

**GUIDANCE DOCUMENTS / MANUALS**IMCA D018-24.3  
IMCA D023. Sheet 11- HP Compressor. Item 4.10

DATE OF INSPECTION	07 <sup>th</sup> March 2025	NEXT DUE DATE:	06 <sup>th</sup> Sept 2027
--------------------	-----------------------------	-------------------	----------------------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE: 