

**FUNCTION / GAS LEAK / VISUAL
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/ Gas leak/ Visual Inspection
CERTIFICATE NUMBER	SADS-FGV-090
ITEM DESCRIPTION	Pressure Relief Safety Valve
ITEM LOCATION	DSV-HPC
SADS ID	DSV-HPC-PRV-05

DESCRIPTION of TEST INSPECTION

2.5 Yearly:

- Full Visual Inspection for corrosion & damage
- Gas leak test to maximum working pressure
- Function Test – Opened at 270 Bar
- Re-seat at 267 Bar

REMARKS / RECOMMENDATIONS

Visual examination to be carried out on a 6 monthly basis, see separate sheet

GUIDANCE DOCUMENTS / MANUALS

IMCA D018-24.3
IMCA D023. Sheet 11- HP Compressor. Item 4.10

DATE OF INSPECTION07th March 2025**NEXT DUE
DATE:**06th Sept 2027**TECHNICIAN NAME:** Dan Zapalski**TECHNICIAN SIGNATURE:** 