



47 Oxbridge Lane,
Stockton on Tees,
Cleveland,
TS18 4AP

Cylinder Test Certificate

Master Cert Number

PFC159

Cylinder No **1**

Customer Details

Name

Sub Aqua Diving Services

Address

17 Tame Road

Lawson Ind Estate

Post Code

Middlesbrough

Phone Number

01642 230209

Cylinder Details

Serial Number

LBC186

Capacity

N/A

Your Reference

Test details

Periodic Inspection and Test

☒

Visual test Only

☐

All test carried out in accordance with EN1802, En1968 or BS5430 pt 6 as applicable and
ASSET CPII

Comments

Visual Examination

Cylinder

External

Good

Satisfactory

Poor

Fail

X

Internal

X

Threads

Valve

X

Cylinder

X

Valve action

Satisfactory

Serviced

Valve Replaced

N/A

N/A

N/A

NDT crack detection
(only required for 6351 Alloy)

Required
Pass

N

N/A

Hydraulic test where applicable:

Required
Pass

Y

Yes

Permanent Set
0%

Results

This cylinder has

Passed

☒

Failed

☐

Date of Test 19 Jul 21

the requirements of the above test

If Passed next Test/Inspection

Re Test Due

Jun 2026

Test type

PIAT

Signed on behalf of the company

DSV-HAC-WS-01-FR-01-FR-01



47 Oxbridge Lane,
Stockton on Tees,
Cleveland,
TS18 4AP

Cylinder Test Certificate

Master Cert Number

PFC159

Cylinder No **2**

Customer Details

Name

Sub Aqua Diving Services

Address

17 Tame Road

Lawson Ind Estate

Post Code

Middlesbrough

Phone Number

01642 230209

Cylinder Details

Serial Number

LDO0914

Capacity

N/A

Your Reference

Test details

Periodic Inspection and Test

☒

Visual test Only

☐

All test carried out in accordance with EN1802, En1968 or BS5430 pt 6 as applicable and
ASSET CPII

Comments

Visual Examination

Cylinder

External

Good

Satisfactory

Poor

Fail

X

Internal

X

Threads

Valve

X

Cylinder

X

Valve action

Satisfactory

Serviced

Valve Replaced

N/A

N/A

N/A

NDT crack detection

(only required for 6351 Alloy)

Required

Pass

N

N/A

Hydraulic test where applicable:

Required

Pass

Y

Yes

Permanent Set

0%

Results

This cylinder has

Passed

☒

Failed

☐

Date of Test 19 Jul 21

the requirements of the above test

If Passed next Test/Inspection

Re Test Due

Jun 2026

Test type

PIAT

Signed on behalf of the company



47 Oxbridge Lane,
Stockton on Tees,
Cleveland,
TS18 4AP

Cylinder Test Certificate

Master Cert Number

PFC159

Cylinder No **3**

Customer Details

Name

Sub Aqua Diving Services

Address

17 Tame Road

Lawson Ind Estate

Post Code

Middlesbrough

Phone Number

01642 230209

Cylinder Details

Serial Number

LDO899

Capacity

N/A

Your Reference

Test details

Periodic Inspection and Test

☒

Visual test Only

☐

All test carried out in accordance with EN1802, En1968 or BS5430 pt 6 as applicable and
ASSET CPII

Comments

Visual Examination

Cylinder

External

Good

Satisfactory

Poor

Fail

X

Internal

X

Threads

Valve

X

Cylinder

X

Valve action

Satisfactory

Serviced

Valve Replaced

N/A

N/A

N/A

NDT crack detection

(only required for 6351 Alloy)

Required

Pass

N

N/A

Hydraulic test where applicable:

Required

Pass

Y

Yes

Permanent Set

0%

Results

This cylinder has

Passed

☒

Failed

☐

Date of Test 19 Jul 21

the requirements of the above test

If Passed next Test/Inspection

Re Test Due

Jun 2026

Test type

PIAT

Signed on behalf of the company