

**FUNCTION / GAS LEAK / VISUAL  
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

|                           |                                       |
|---------------------------|---------------------------------------|
| TYPE OF TEST / INSPECTION | Function/ Gas leak/ Visual Inspection |
| CERTIFICATE NUMBER        | SADS-FGV-078                          |
| ITEM DESCRIPTION          | Pressure Relief Safety Valve          |
| ITEM LOCATION             | Low pressure receiver Diver 2         |
| SADS ID                   | SADS-LPR-PRV-02                       |
| TEST DEVICE USED          | Druck serial No 3219487 SADS T&T 04   |

**DESCRIPTION of TEST INSPECTION**

2.5 Yearly:

- Full Visual Inspection for corrosion & damage
- Gas leak test to maximum working pressure (13 Bar)
- Function Test – Opened at 16.10 Bar
- Re-seat at 14.52 Bar

**REMARKS / RECOMMENDATIONS**

Visual examination to be carried out on a 6 monthly basis, see separate sheet

**GUIDANCE DOCUMENTS / MANUALS**

IMCA D018-24.3  
IMCA D023- Sheet 11-(LP) Atlas Copco Compressor. Item 4.10

|                    |                             |                   |                            |
|--------------------|-----------------------------|-------------------|----------------------------|
| DATE OF INSPECTION | 05 <sup>th</sup> March 2025 | NEXT DUE<br>DATE: | 04 <sup>th</sup> Sept 2027 |
|--------------------|-----------------------------|-------------------|----------------------------|

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE: 