



FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual Inspection
CERTIFICATE NUMBER	SADS-FGV-074
ITEM DESCRIPTION	Low Pressure Receiver Diver 2 (S/n 07129)
ITEM LOCATION	Engine room DSV Curtis Marshall
SADS ID	DSV-LPR-02
TEST DEVICE USED	LP Compressor then HP cylinder and Regulator

DESCRIPTION of TEST INSPECTION

2½ yearly visual and gas leak carried out, in line with the 5 yearly overpressure tests conducted by SMP.
Full internal visual using an endoscope Prior to over pressure test.

REMARKS / RECOMMENDATIONS

Vessel is in as new condition with no rust or discolouration present

GUIDANCE DOCUMENTS / MANUALS

IMCA D018-26
IMCA D023. Sheet 11. (LP) Atlas Copco Compressor. Item 6.3

DATE OF INSPECTION	05 th March 2025	NEXT DUE DATE:	04 th Sept 2027
--------------------	-----------------------------	----------------	----------------------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

