

FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020

Issue Date: 28/05/2020 Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual		
CERTIFICATE NUMBER	SADS-FGV-975		
ITEM	12 Litre HP Cylinder		
ITEM DESCRIPTION	Bailout Cylinder		
ITEM LOCATION	Workshop		
SADS ID	SADS-HPB-30		

DESCRIPTION of TEST INSPECTION

2.5 Yearly visual inspection and gas leak test in line with 5 yearly hydro. Gas leak tests to maximum working pressure were carried out. All work carried out and certified in house.

REMARKS / RECOMMENDATIONS

6 monthly visual inspections to be carried out. See 6 monthly certification.

GUIDANCE DOCUMENTS / MANUALS

Above carried out IAW IMCA D018 - 9.1

DATE OF INSPECTION	15 th April 2024	NEXT DUE DATE:	14th Oct 2026
--------------------	-----------------------------	-----------------------	---------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

77/

Sub Aquatamp

Tech Dept

Sub Aquatamp

Diving Services

Sub Aqua Diving Services UK Ltd E: enquiries@commercialdivingservices.co.uk

W: www.commercialdivingservices.co.uk