

4th Element

32

47 Oxbridge Lane, Stockton on Tees, Cleveland, TS18 4AP
01642 601616 / 07808 170 357

Cylinder Test Certificate

Job No. _____

Owners Name Mr/Mrs/Ms _____ Forename/initials _____

Owners Address SUB AQUA DIVING SERVICES

Post Code _____ Phone No. _____

Make ROTH Ser No 74972 Capacity 12 litre

A Periodic Inspection and Test ☐ or Visual Inspection Only ☐ was carried in accordance with EN 1802, EN 1968 or BS 5430 Pt 6 as applicable and ASSET CP 2.

Comments

Visual: External condition: Good ☐ Satisfactory ☒ Poor ☐ Fail ☐

Visual: Internal condition: Good ☐ Satisfactory ☒ Poor ☐ Fail ☐

Threads: Valve: Good ☐ Satisfactory ☒ Poor ☐ Fail ☐

Threads: Cylinder: Good ☐ Satisfactory ☒ Poor ☐ Fail ☐

Valve action: Satisfactory ☒ Serviced Y ☒ N ☐ Valve replaced: Y ☐ N ☐

NDT Crack Detection Y ☐ N ☒ (Only required for 8351 aluminium) Pass ☐ Fail ☐

Hydraulic test where applicable: Pass ☒ Fail ☐ Permanent Set 0 %

This cylinder has Passed ☒ Failed ☐ the requirements of the above inspection or test

If passed, next Test/Inspection due date 09/2017

Signed on behalf of the company [Signature] Date 7/4/15

Copyright © 1994 – 2002 STATS 2000/C S Meinert

