

**FUNCTION / GAS LEAK / VISUAL  
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

<b>TYPE OF TEST / INSPECTION</b>	Function/Gas Leak/Visual
<b>CERTIFICATE NUMBER</b>	<b>SADS-FGV-978</b>
<b>ITEM</b>	12 Litre HP Cylinder
<b>ITEM DESCRIPTION</b>	Bailout Cylinder
<b>ITEM LOCATION</b>	Workshop
<b>SADS ID</b>	<b>SADS-HPB-36</b>

**DESCRIPTION of TEST INSPECTION**

2.5 Yearly visual inspection and gas leak test in line with 5 yearly hydro.  
Gas leak tests to maximum working pressure were carried out.  
All work carried out and certified in house.

**REMARKS / RECOMMENDATIONS**

6 monthly visual inspections to be carried out. See 6 monthly certification.

**GUIDANCE DOCUMENTS / MANUALS**

Above carried out IAW IMCA D018 – 9.1

**DATE OF INSPECTION**15<sup>th</sup> April 2024**NEXT DUE DATE:**14<sup>th</sup> Oct 2026**TECHNICIAN NAME:** Dan Zapalski**TECHNICIAN SIGNATURE:**