

FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020 Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual	
CERTIFICATE NUMBER	SADS-FGV-865	eene Me
ITEM DESCRIPTION	HP Quad Pipework and Fittings	
ITEM LOCATION	SADS-HPQ-01	
SADS ID	DSV-HPQ-01-PW	
TEST DEVICE USED	System Pressure	

DESCRIPTION of TEST INSPECTION

All pipework and fittings stripped and cleaned, flushed through with 20/80 percent biox and water solution and blown through dry with fresh air.

2 yearly pressure test IAW IMCA D018-24.1

No leaks

Working Pressure - 200 Bar

Test Pressure - Maximum rated working pressure

Test Duration - 1 Hour

Test Result - Pass

REMARKS / RECOMMENDATIONS

Pre dive checks carried out daily when system in operation 6 monthly checks carried out in line with 6m paperwork

GUIDANCE DOCUMENTS / MANUALS

IMCA D018 24.1

Pipework and fittings cleaned to Oxygen use standards on re-assembly after hydrostatic testing

DATE OF INSPECTION 28th Feb 2023 NEXT DUE DATE: 27th Feb 2025

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

Tech Dept
Sub Aquatama
Diving Services