

## FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020 Issued By: P. Curtis

<b>TYPE OF TEST / INSPECTION</b>	Function/Gas Leak/Visual and Pressure Test			
CERTIFICATE NUMBER	CATE NUMBER SADS-FGV-914			
ITEM	HP Quad 04 Pipework and Fittings			
ITEM LOCATION	DSV Curtis Marshall – DDC Back Up			
SADS ID	SADS-HPQ-04-PW			

## **DESCRIPTION of TEST INSPECTION**

2 yearly pressure test, function check, and visual inspection. No leaks.

Working Pressure – 200 Bar Test Pressure – 200 Bar Test Equipment – HP Air

## **REMARKS / RECOMMENDATIONS**

System all ok.

6 monthly checks to be carried out.

Daily checks to be carried out in accordance with daily chamber checks during diving operations.

## **GUIDANCE DOCUMENTS / MANUALS**

IMCA D018 24.1

DATE OF INSPECTION	31 <sup>st</sup> August 2023	NEXT DUE DATE:	30 <sup>th</sup> August 2025		

TECHNICIAN NAME: Dan Zapalski

**TECHNICIAN SIGNATURE:** 

Tech Dept
Sub Aquamp
Diving Services

Sub Aqua Diving Services UK Ltd E: <a href="mailto:enquiries@commercialdivingservices.co.uk">enquiries@commercialdivingservices.co.uk</a>

W: www.commercialdivingservices.co.uk