

Certificate Of Cleanliness

Doc Ref: SADS-IMS-FM-91

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

CERTIFICATE NUMBER	SADS-CL-02
ITEM DESCRIPTION	High Pressure Pipework
ITEM LOCATION	DSV Curtis Marshall – divers HP supply
SADS ID	SADS-HPQ-04-PW
SERIAL NO. / MODEL NO.	

DETAILS OF WORK UNDERTAKEN:

In line with the 2.5 yearly internal visual inspection of SADS-HPQ cylinders. The pipework was removed and cleaned in a solution of 20% Biox and water.

Pipework was then flushed with fresh water and blown dry before re-fitting.

Cylinders due 5 yearly Hydro in December 22, reclean pipework in line with test.


ITEM	COMMENTS	RESULTS	INITIAL

REMARKS OR RECOMMENDATIONS:

Documents referred to D 018 24.1 & D 031
Biox O2 liquid cleaning procedure section 2

DATE OF INSPECTION	15 th June 2020	NEXT DUE DATE:	When required (next unit overhaul or component change out)
--------------------	----------------------------	----------------	--

TECHNICIAN NAME: Neil Graham

TECHNICIAN SIGNATURE: 

Sub Aqua Diving Services (UK) Ltd