

FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92 Issue 01 Issue Date: 28/05/2020 Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function, Gas Leak, Visual		
CERTIFICATE NUMBER	SADS-FGV-013		
ITEM	10m charging whip		
ITEM LOCATION	DSV Curtis Marshall		
SADS ID	SADS/HPW/10		
TEST DEVICE USED	HP Compressor		

DESCRIPTION of TEST INSPECTION

2 Yearly:

High pressure whip tested to MWP of 232 bar

Visual inspection and leak check carried out, all found ok

REMARKS / RECOMMENDATIONS

Not included in EPM front sheet (Spare)

GUIDANCE DOCUMENTS / MANUALS


IMCA DO18 24.1

DATE OF INSPECTION	16th Oct 2024	NEXT DUE	15th Oct 2026
	Allow The Property of	DATE:	

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

736



Sub Aqua Diving Services UK Ltd
E: enquiries@commercialdivingservices.co.uk
W: www.commercialdivingservices.co.uk