

FUNCTION / GAS LEAK / VISUAL TEST CERTIFICATE

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function, Gas Leak, Visual
CERTIFICATE NUMBER	SADS-FGV-573
ITEM	10m charging whip
ITEM LOCATION	DSV Curtis Marshall
SADS ID	SADS/HPW/34
TEST DEVICE USED	HP Compressor

DESCRIPTION of TEST INSPECTION

High pressure whip tested to MWP of 232 bar
Visual inspection and leak check carried out, all found ok

REMARKS / RECOMMENDATIONS

GUIDANCE DOCUMENTS / MANUALS

IMCA DO18 24.1

DATE OF INSPECTION

23rd Sept 2020

NEXT DUE DATE:

22nd Sept 2022

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE:

