

CERTIFICATE OF CLEANLINESS

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual and Cleanliness Verification
CERTIFICATE NUMBER	SADS-FGV-834
ITEM DESCRIPTION	DDC O2 Supply Hose
ITEM LOCATION	DSV Curtis Marshall
SERIAL NO	ESC30546
SADS ID	SADS-O2W-06
TEST DEVICE USED	HPQ 01 and hose flushing system

DESCRIPTION of TEST INSPECTION

- Full Visual Inspection for corrosion & damage
- Whip disconnected and flushed with a solution of water and Biox then blown through with LP regulated air until dry
- 2 Yearly: Gas leak test to maximum working pressure (18 Bar g – 15mins)

REMARKS / RECOMMENDATIONS

6 monthly checks to be carried out IAW asset file paperwork
Visual and function tests to be carried out as per pre dive checks
Note that hose has not been flushed with o2 but cleaned and flushed with air and capped off.

GUIDANCE DOCUMENTS / MANUALS

Above carried out IAW IMCA D018-28

DATE OF INSPECTION	10 th Aug 2021	NEXT DUE DATE:	09 th Aug 2023
--------------------	---------------------------	----------------	---------------------------

TECHNICIAN NAME: Dan Zapalski

TECHNICIAN SIGNATURE: 