

**FUNCTION / GAS LEAK / VISUAL  
TEST CERTIFICATE**

Doc Ref: SADS-IMS-FM-92

Issue 01

Issue Date: 28/05/2020

Issued By: P. Curtis

TYPE OF TEST / INSPECTION	Function/Gas Leak/Visual
CERTIFICATE NUMBER	SADS-FGV-906
ITEM	Fibron 175 metre Divers Umbilical
ITEM LOCATION	DSV Curtis Marshall
SADS ID	SADS-UMB-07
SERIAL No. / MODEL No.	10700/1

**DESCRIPTION of TEST INSPECTION**

External visual inspection all ferrules and fittings checked.  
2 yearly pressure tests to MWP by capping off and pressurising on air to 20 BAR.  
Umbilical were then leak tested at working pressure of 20 BAR for 30 minutes.  
No leaks evident and no "blebbing" of hose along its length.  
O2 Cleanliness verified.  
Camera, lights, and communications all checked and working satisfactorily.

**REMARKS / RECOMMENDATIONS**

6 monthly inspections carried out alongside 2 yearly inspections.

**GUIDANCE DOCUMENTS / MANUALS**

Above carried out IAW IMCA D018-28

DATE OF INSPECTION	31 <sup>st</sup> August 2023	NEXT DUE DATE:	30 <sup>th</sup> August 2025
--------------------	------------------------------	-------------------	------------------------------

TECHNICIAN NAME: N Graham/ Dan Zapalski

TECHNICIAN SIGNATURE: 